



**USCG Icebreaker Support Contract
DTCG85-00-D-66P381
Condition Found Report**

CFR Title: Modify .322 Sheave with new inserts
Vessel: USCGC Healy (WAGB 20)

CFR Date: March 7, 2004
CFR N^o: DO 029-004

Statement of Condition Found

The 24" flag block in the CTD staging area was not included in the recent sheave modifications that allow passing of Fiege fitting.

Recommended Action

A proper design should be made of a modification to the existing 24" flag block sheave to allow passing of the attached end fitting. Ship to provide details of such a fitting for the design.
Upon design completion, construct replacement sheave inserts (and spare inserts) for the 24" flag block.
During the next availability the new inserts should be installed.

Prepared by: Ron White, Director of Operations, InterOcean Systems, Inc.

Work breakdown Attached? (Y/N)

Customer Reply

Customer Signature & Date _____